Antiproton Source Work list

D. Vander Meulen 05/23/03

Access Items

Work To Perform	Person Responsible	Location	Time	Key	Comments
			Required	Requirements	
AP2 Alignment work	Harms	Transport	2 days	3 Rings /	
		(Rings?)		3 Transport	
Repair LCW leaks on	Harms	Rings	1 hr	2 Rings	Requires magnet
A5Q2 & D6Q11		_			factory people
Inspection / maint for					This should be done
AP2 roughing pump	Gusler	Transport	1 hr	2 Transport	as the opportunity presents itself
Inspection of	Budlong	Rings	2 hrs	2 Rings	
Debuncher BPMs					
RF system	Vargo	$A40 \rightarrow A50$	2 hrs	2 Rings	
maintenance					
Change out		AP0			2 techs, 1 rad tech
conductivity cell in	Morgan	Target Hall	2 hrs		
lens water system					
Change target air	Morgan	AP0	1 hr		1 tech, 1 rad tech
pressure transducer		Target Hall			
Move the U/S end of					This is contingent on
D:ISEP and connect	Vander Meulen	D40	2 hrs	2 Rings	AP2 alignment work
D/S end of D-chamber					findings.
to motion control					
Inspect Lens module	Leveling	Target Vault	1 day	Vault	
for leaks	Morgan	_			
Inspect 4-8 core					
momentum TWT	P. Seifrid	A40	1 day	2 Rings	
water flow tripping					
Label electronics	P. Seifrid	D10, D30	1 hr	2 Rings	
assemblies		,			
Inspect target module	Morgan	AP0	5 hrs		2 techs, 1 rad tech.
		Target Hall			Low priority

Systems Maintenance Items

Work To Perform	Person Responsible	Location	Time Required	Key Requirements	Comments
Sublimate Acc sectors, general vacuum maint as needed	Gusler	Rings	1 hr	N/A	Dayshifts when the stack is small
Recabling work on ARF1 / DRF1 low- level	B. Vargo	AP50	N/A	N/A	
Modify interlock chassis: A:IB, D:IB, A:LQ, A:QDF, A:QT, D:QD, D:QF, D:QSS	B. Wisner	Service Buildings		N/A	
LCW O2 removal system maintenance	FESS	CUB	?	N/A	
Wet engine maintenance	Harms / Makara	AP30	1 hr	N/A	

Replace chilled water skid	Harms	AP30	2 days	N/A	Upgrade over existing skid
Switch to newplate / frame heat exchanger	Harms	CUB	30 minutes	N/A	
Repair D:H4TH01 readback	Mueller	AP30	30 minutes	N/A	Bad burndy connection in motor controller crate
Testing of new DRF1 cavity tuning control system	Vander Meulen / Harms	AP50	As needed	N/A	As time permits
Install new SWIC scanner chassies	Sondgeroth	AP30, AP50	1 day	N/A	